

# Move In

leasing@utahpropertyolutions.com  
Utah Property Solutions  
1226 W. South Jordan Pkwy, Ste D, South Jordan, Utah 84095  
(801) 701-8033  
(801) 701-8032



| Property     | Tenant(s) | Date       | Agent / Inspector |
|--------------|-----------|------------|-------------------|
| Victoria Way |           | 2025-06-03 | Nils Adey         |

## Move-In Conditions

✓ S=Satisfactory

## Move In Condition Summary

| Area  | Detail         | Condition | Actions     | Comment             | Media                 |
|-------|----------------|-----------|-------------|---------------------|-----------------------|
| Entry | Door/Knob/Lock | ✓ S       | Maintenance | Screen needs repair | <a href="#">Image</a> |

Back Yard/Exterior

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Building Exterior  | ✓ S       | None    |         |
| Fence/Gate         | ✓ S       | None    |         |
| Landscaping        | ✓ S       | None    |         |
| Light Fixture      | ✓ S       | None    |         |
| Other              | ✓ S       | None    |         |
| Patio/Deck/Balcony | ✓ S       | None    |         |
| Walkway            | ✓ S       | None    |         |



2025-06-03 13:03:12  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:03:16  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:03:18  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:03:30  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:03:32  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:03:49  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:03:51  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:04:05  
40.7951061, -111.9192167  
[View Image](#)




2025-06-03 13:04:09  
40.7951061, -111.9192167  
[View Image](#)



2025-06-03 13:04:35  
40.7951061, -111.9192167  
[View Image](#)

## Bathroom: Hall bathroom

| Detail                   | Condition | Actions | Comment |
|--------------------------|-----------|---------|---------|
| Cabinet/Counter/Shelving | ✓ S       | None    |         |
| Door/Knob/Lock           | ✓ S       | None    |         |
| Exhaust Fan              | ✓ S       | None    |         |
| Flooring/Baseboard       | ✓ S       | None    |         |
| Light Fixture            | ✓ S       | None    |         |
| Medicine Cabinet/Mirror  | ✓ S       | None    |         |
| Other                    | ✓ S       | None    |         |
| Plumbing/Drain           | ✓ S       | None    |         |
| Shower Door/Rail/Curtain | ✓ S       | None    |         |
| Sink/Faucet              | ✓ S       | None    |         |
| Switch/Outlet            | ✓ S       | None    |         |
| Toilet                   | ✓ S       | None    |         |
| Toilet Paper Holder      | ✓ S       | None    |         |
| Towel Rack               | ✓ S       | None    |         |
| Tub/Shower               | ✓ S       | None    |         |
| Wall/Ceiling             | ✓ S       | None    |         |



2025-06-03 12:01:23  
[40.7953072, -111.9189762](#)  
[360 Viewer](#)



2025-06-03 12:01:44  
[40.7953072, -111.9189762](#)  
[360 Viewer](#)



2025-06-03 12:11:13  
40.7952437, -111.91903  
[View Image](#)



2025-06-03 12:11:22  
40.7952437, -111.91903  
[View Image](#)



2025-06-03 12:11:31  
40.7952437, -111.91903  
[View Image](#)



2025-06-03 12:11:37  
40.7952437, -111.91903  
[View Image](#)




2025-06-03 12:11:42  
40.7952437, -111.91903  
[View Image](#)



2025-06-03 12:11:50  
40.7952437, -111.91903  
[View Image](#)



2025-06-03 12:12:07  
40.7952437, -111.91903  
[View Image](#)



2025-06-03 12:58:51  
40.7952991, -111.9190899  
[View Image](#)

## Bathroom 2: Master bathroom

| Detail                   | Condition | Actions | Comment |
|--------------------------|-----------|---------|---------|
| Cabinet/Counter/Shelving | ✓ S       | None    |         |
| Door/Knob/Lock           | ✓ S       | None    |         |
| Exhaust Fan              | ✓ S       | None    |         |
| Flooring/Baseboard       | ✓ S       | None    |         |
| Light Fixture            | ✓ S       | None    |         |
| Medicine Cabinet/Mirror  | ✓ S       | None    |         |
| Other                    | ✓ S       | None    |         |
| Plumbing/Drain           | ✓ S       | None    |         |
| Shower Door/Rail/Curtain | ✓ S       | None    |         |
| Sink/Faucet              | ✓ S       | None    |         |
| Switch/Outlet            | ✓ S       | None    |         |
| Toilet                   | ✓ S       | None    |         |
| Toilet Paper Holder      | ✓ S       | None    |         |
| Towel Rack               | ✓ S       | None    |         |

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Tub/Shower         | ✓ S       | None    |         |
| Wall/Ceiling       | ✓ S       | None    |         |
| Window Covering    | ✓ S       | None    |         |
| Window/Lock/Screen | ✓ S       | None    |         |



2025-06-03 12:00:54  
[40.7953072, -111.9189762](#)  
[360 Viewer](#)



2025-06-03 12:13:58  
[40.7952553, -111.9190168](#)  
[View Image](#)



2025-06-03 12:14:15  
[40.7952553, -111.9190168](#)  
[View Image](#)



2025-06-03 12:14:33  
[40.7952553, -111.9190168](#)  
[View Image](#)



2025-06-03 12:14:41  
40.7952553, -111.9190168  
[View Image](#)



2025-06-03 12:14:48  
40.7952553, -111.9190168  
[View Image](#)



2025-06-03 12:14:57  
40.7952553, -111.9190168  
[View Image](#)



2025-06-03 12:15:09  
40.7952553, -111.9190168  
[View Image](#)



2025-06-03 12:59:13  
40.7952991, -111.9190899  
[View Image](#)

## Entry

| Detail               | Condition | Actions     | Comment             |
|----------------------|-----------|-------------|---------------------|
| Door/Knob/Lock       | ✓ S       | Maintenance | Screen needs repair |
| Doorbell             | ✓ S       | None        |                     |
| Flooring/Baseboard   | ✓ S       | None        |                     |
| Light Fixture/Fan    | ✓ S       | None        |                     |
| Other                | ✓ S       | None        |                     |
| Security/Screen Door | ✓ S       | None        |                     |
| Switch/Outlet        | ✓ S       | None        |                     |
| Wall/Ceiling         | ✓ S       | None        |                     |



2025-06-03 13:05:14  
40.7952207, -111.9192473  
[View Image](#)



2025-06-03 13:05:29  
40.7952207, -111.9192473  
[View Image](#)



2025-06-03 13:06:06  
40.7952207, -111.9192473  
[View Image](#)



2025-06-03 13:07:18  
40.7951034, -111.9191406  
[View Image](#)



2025-06-03 13:09:28  
40.7953614, -111.919101  
[View Image](#)



**Door/Knob/Lock**  
2025-06-03 13:09:42  
40.7953614, -111.919101  
[View Image](#)

## Bedroom: Master bathroom

| Detail                     | Condition | Actions | Comment |
|----------------------------|-----------|---------|---------|
| Closet/Door/Track/Shelving | ✓ S       | None    |         |
| Door/Knob/Lock             | ✓ S       | None    |         |
| Flooring/Baseboard         | ✓ S       | None    |         |
| Light Fixture/Fan          | ✓ S       | None    |         |
| Other                      | ✓ S       | None    |         |
| Smoke/CO Detector          | ✓ S       | None    |         |
| Switch/Outlet              | ✓ S       | None    |         |

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Wall/Ceiling       | ✓ S       | None    |         |
| Window Covering    | ✓ S       | None    |         |
| Window/Lock/Screen | ✓ S       | None    |         |



2025-06-03 12:00:08  
[40.7952085, -111.9188844](#)  
[360 Viewer](#)



2025-06-03 12:00:28  
[40.7952085, -111.9188844](#)  
[360 Viewer](#)



2025-06-03 12:16:23  
[40.7952869, -111.9191651](#)  
[View Image](#)



2025-06-03 12:16:26  
[40.7952869, -111.9191651](#)  
[View Image](#)



2025-06-03 12:16:31  
[40.7952869, -111.9191651](#)  
[View Image](#)



2025-06-03 12:16:36  
[40.7952869, -111.9191651](#)  
[View Image](#)

Bedroom 2: First on right

| Detail                     | Condition | Actions | Comment |
|----------------------------|-----------|---------|---------|
| Closet/Door/Track/Shelving | ✓ S       | None    |         |
| Door/Knob/Lock             | ✓ S       | None    |         |
| Flooring/Baseboard         | ✓ S       | None    |         |
| Light Fixture/Fan          | ✓ S       | None    |         |
| Other                      | ✓ S       | None    |         |
| Smoke/CO Detector          | ✓ S       | None    |         |
| Switch/Outlet              | ✓ S       | None    |         |
| Wall/Ceiling               | ✓ S       | None    |         |
| Window Covering            | ✓ S       | None    |         |
| Window/Lock/Screen         | ✓ S       | None    |         |



2025-06-03 11:59:37  
[40.7952085, -111.9188844](#)  
[360 Viewer](#)



2025-06-03 12:18:45  
[40.7952719, -111.919172](#)  
[View Image](#)



2025-06-03 12:18:51  
 40.7952719, -111.919172  
[View Image](#)

### Bedroom 3: End of hall

| Detail                     | Condition | Actions | Comment |
|----------------------------|-----------|---------|---------|
| Closet/Door/Track/Shelving | ✓ S       | None    |         |
| Door/Knob/Lock             | ✓ S       | None    |         |
| Flooring/Baseboard         | ✓ S       | None    |         |
| Light Fixture/Fan          | ✓ S       | None    |         |
| Smoke/CO Detector          | ✓ S       | None    |         |
| Switch/Outlet              | ✓ S       | None    |         |
| Wall/Ceiling               | ✓ S       | None    |         |
| Window Covering            | ✓ S       | None    |         |
| Window/Lock/Screen         | ✓ S       | None    |         |



2025-06-03 11:58:43  
 40.7952085, -111.9188844  
[360 Viewer](#)



2025-06-03 11:59:02  
 40.7952085, -111.9188844  
[360 Viewer](#)



2025-06-03 12:17:18  
40.7952869, -111.9191651  
[View Image](#)



2025-06-03 12:17:22  
40.7952869, -111.9191651  
[View Image](#)



2025-06-03 12:17:27  
40.7952869, -111.9191651  
[View Image](#)



2025-06-03 12:17:31  
40.7952869, -111.9191651  
[View Image](#)

## Dining Room

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Cleaning Required  | ✓ S       | None    |         |
| Flooring/Baseboard | ✓ S       | None    |         |
| Light Fixture/Fan  | ✓ S       | None    |         |
| Switch/Outlet      | ✓ S       | None    |         |
| Wall/Ceiling       | ✓ S       | None    |         |
| Window Covering    | ✓ S       | None    |         |
| Window/Lock/Screen | ✓ S       | None    |         |



2025-06-03 11:56:02  
40.7951744, -111.9190971  
360 Viewer




2025-06-03 12:21:02  
40.7952886, -111.9191591  
[View Image](#)



2025-06-03 12:21:06  
40.7952886, -111.9191591  
[View Image](#)



2025-06-03 12:21:10  
40.7952886, -111.9191591  
[View Image](#)



2025-06-03 12:21:21  
40.7952886, -111.9191591  
[View Image](#)



2025-06-03 12:22:51  
40.7952902, -111.9191448  
[View Image](#)

Front Yard/Exterior

| Detail            | Condition | Actions | Comment |
|-------------------|-----------|---------|---------|
| Building Exterior | ✓ S       | None    |         |
| Landscaping       | ✓ S       | None    |         |
| Light Fixture     | ✓ S       | None    |         |
| Walk/Driveway     | ✓ S       | None    |         |



2025-06-03 13:08:07  
40.7951034, -111.9191406  
[View Image](#)



2025-06-03 13:08:16  
40.7951034, -111.9191406  
[View Image](#)



2025-06-03 13:08:18  
40.7951034, -111.9191406  
[View Image](#)



2025-06-03 13:08:31  
40.7951034, -111.9191406  
[View Image](#)



2025-06-03 13:08:50  
[40.7951034, -111.9191406](#)  
[View Image](#)



2025-06-03 13:09:00  
[40.7951034, -111.9191406](#)  
[View Image](#)

## Garage/Parking: Carport

| Detail         | Condition | Actions | Comment |
|----------------|-----------|---------|---------|
| Driveway/Floor | ✓ S       | None    |         |
| Light Fixture  | ✓ S       | None    |         |
| Other          | ✓ S       | None    |         |
| Switch/Outlet  | ✓ S       | None    |         |




2025-06-03 12:04:17  
[40.795247, -111.91903](#)  
[360 Viewer](#)



2025-06-03 13:07:33  
[40.7951034, -111.9191406](#)  
[View Image](#)



2025-06-03 13:07:43  
40.7951034, -111.9191406  
[View Image](#)



2025-06-03 13:07:51  
40.7951034, -111.9191406  
[View Image](#)

## Hallway/Stairs

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Flooring/Baseboard | ✓ S       | None    |         |
| Light Fixture      | ✓ S       | None    |         |
| Other              | ✓ S       | None    |         |
| Smoke/CO Detector  | ✓ S       | None    |         |
| Switch/Outlet      | ✓ S       | None    |         |
| Wall/Ceiling       | ✓ S       | None    |         |



2025-06-03 11:53:38  
40.7952489, -111.919151  
[360 Viewer](#)



2025-06-03 11:54:02  
40.7952489, -111.919151  
[360 Viewer](#)



2025-06-03 11:54:35  
40.7951744, -111.9190971  
[360 Viewer](#)



2025-06-03 12:58:13  
40.7952991, -111.9190899  
[View Image](#)



2025-06-03 12:58:21  
40.7952991, -111.9190899  
[View Image](#)




2025-06-03 12:58:25  
40.7952991, -111.9190899  
[View Image](#)




2025-06-03 12:58:29  
40.7952991, -111.9190899  
[View Image](#)

## Keys/Remotes/Devices

| Detail          | Condition | Actions | Comment |
|-----------------|-----------|---------|---------|
| Keys            | ✓ S       | None    |         |
| Remotes/Devices | ✓ S       | None    |         |



2025-06-03 12:22:27  
40.7952886, -111.9191591  
[View Image](#)



2025-06-03 13:01:19  
40.7953031, -111.9190493  
[View Image](#)

## Kitchen

| Detail             | Condition | Actions | Comment                                    |
|--------------------|-----------|---------|--------------------------------------------|
| Cabinets/Drawers   | ✓ S       | None    | Baseboards need repair / replace / paint.h |
| Counter            | ✓ S       | None    |                                            |
| Dishwasher         | ✓ S       | None    |                                            |
| Faucet/Plumbing    | ✓ S       | None    |                                            |
| Flooring/Baseboard | ✓ S       | None    |                                            |
| Light Fixture      | ✓ S       | None    |                                            |
| Microwave          | ✓ S       | None    |                                            |
| Oven               | ✓ S       | None    |                                            |
| Pantry / Shelves   | ✓ S       | None    |                                            |
| Refrigerator       | ✓ S       | None    |                                            |

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Sink/Disposal      | ✓ S       | None    |         |
| Switch/Outlet      | ✓ S       | None    |         |
| Wall/Ceiling       | ✓ S       | None    |         |
| Window Covering    | ✓ S       | None    |         |
| Window/Lock/Screen | ✓ S       | None    |         |



2025-06-03 11:56:23  
[40.7951744, -111.9190971](#)  
 360 Viewer



2025-06-03 11:56:45  
[40.7951744, -111.9190971](#)  
 360 Viewer



Cabinets/Drawers  
 2025-06-03 12:49:22  
[40.7950565, -111.9190649](#)  
[View Image](#)



Cabinets/Drawers  
 2025-06-03 12:49:33  
[40.7950565, -111.9190649](#)  
[View Image](#)



**Cabinets/Drawers**  
 2025-06-03 12:49:46  
 40.7950565, -111.9190649  
[View Image](#)



**Cabinets/Drawers**  
 2025-06-03 12:49:56  
 40.7950565, -111.9190649  
[View Image](#)



**Cabinets/Drawers**  
 2025-06-03 12:50:06  
 40.7950565, -111.9190649  
[View Image](#)



**Cabinets/Drawers**  
 2025-06-03 12:50:16  
 40.7950565, -111.9190649  
[View Image](#)



**Cabinets/Drawers**  
 2025-06-03 12:50:32  
 40.7950565, -111.9190649  
[View Image](#)



**Cabinets/Drawers**  
 2025-06-03 12:50:44  
 40.7952471, -111.9191112  
[View Image](#)



**Cabinets/Drawers**  
2025-06-03 12:50:57  
[40.7952471, -111.9191112](#)  
[View Image](#)



**Cabinets/Drawers**  
2025-06-03 12:50:59  
[40.7952471, -111.9191112](#)  
[View Image](#)



**Cabinets/Drawers**  
2025-06-03 12:53:51  
[40.795185, -111.9189763](#)  
[View Image](#)



**Cabinets/Drawers**  
2025-06-03 12:53:57  
[40.795185, -111.9189763](#)  
[View Image](#)



**Cabinets/Drawers**  
2025-06-03 12:54:05  
[40.795185, -111.9189763](#)  
[View Image](#)



**Cabinets/Drawers**  
2025-06-03 12:54:11  
[40.795185, -111.9189763](#)  
[View Image](#)



Counter  
2025-06-03 12:54:23  
40.795185, -111.9189763  
[View Image](#)



Counter  
2025-06-03 12:54:29  
40.795185, -111.9189763  
[View Image](#)



Counter  
2025-06-03 12:54:33  
40.795185, -111.9189763  
[View Image](#)



Counter  
2025-06-03 12:54:36  
40.795185, -111.9189763  
[View Image](#)



Counter  
2025-06-03 12:54:43  
40.795185, -111.9189763  
[View Image](#)



Counter  
2025-06-03 12:54:52  
40.795185, -111.9189763  
[View Image](#)



**Counter**  
2025-06-03 12:54:58  
[40.795185, -111.9189763](#)  
[View Image](#)



**Counter**  
2025-06-03 12:55:03  
[40.795185, -111.9189763](#)  
[View Image](#)



**Dishwasher**  
2025-06-03 12:55:18  
[40.795185, -111.9189763](#)  
[View Image](#)



**Dishwasher**  
2025-06-03 12:55:26  
[40.795185, -111.9189763](#)  
[View Image](#)



**Dishwasher**  
2025-06-03 12:55:29  
[40.795185, -111.9189763](#)  
[View Image](#)



**Dishwasher**  
2025-06-03 12:55:34  
[40.795185, -111.9189763](#)  
[View Image](#)



Oven  
2025-06-03 12:55:51  
[40.7952588, -111.9191107](#)  
[View Image](#)



Oven  
2025-06-03 12:55:56  
[40.7952588, -111.9191107](#)  
[View Image](#)



Oven  
2025-06-03 12:55:58  
[40.7952588, -111.9191107](#)  
[View Image](#)



Oven  
2025-06-03 12:56:06  
[40.7952588, -111.9191107](#)  
[View Image](#)



Oven  
2025-06-03 12:56:12  
[40.7952588, -111.9191107](#)  
[View Image](#)



Refrigerator  
2025-06-03 12:56:27  
[40.7952588, -111.9191107](#)  
[View Image](#)



**Refrigerator**  
2025-06-03 12:56:32  
[40.7952588, -111.9191107](#)  
[View Image](#)



**Refrigerator**  
2025-06-03 12:56:42  
[40.7952588, -111.9191107](#)  
[View Image](#)



**Refrigerator**  
2025-06-03 12:56:46  
[40.7952588, -111.9191107](#)  
[View Image](#)



**Refrigerator**  
2025-06-03 12:56:54  
[40.7952588, -111.9191107](#)  
[View Image](#)



**Refrigerator**  
2025-06-03 12:56:57  
[40.7952588, -111.9191107](#)  
[View Image](#)



**Refrigerator**  
2025-06-03 12:57:03  
[40.7952588, -111.9191107](#)  
[View Image](#)



### Refrigerator

2025-06-03 12:57:09

40.7952588, -111.9191107


[View Image](#)

## Laundry Room

| Detail                   | Condition | Actions | Comment                               |
|--------------------------|-----------|---------|---------------------------------------|
| Cabinet/Counter/Shelving | ✓ S       | None    |                                       |
| Door/Knob/Lock           | ✓ S       | None    |                                       |
| Dryer                    | ✓ S       | None    |                                       |
| Faucet/Valve             | ✓ S       | None    |                                       |
| Flooring/Baseboard       | ✓ S       | None    |                                       |
| Light Fixture/Fan        | ✓ S       | None    | I changed bulb, could not find switch |
| Plumbing/Drain           | ✓ S       | None    |                                       |
| Switch/Outlet            | ✓ S       | None    |                                       |
| Wall/Ceiling             | ✓ S       | None    |                                       |
| Washer                   | ✓ S       | None    |                                       |
| Window Covering          | ✓ S       | None    |                                       |
| Window/Lock/Screen       | ✓ S       | None    |                                       |



2025-06-03 11:57:51  
[40.7951744, -111.9190971](#)  
[360 Viewer](#)



2025-06-03 12:23:25  
[40.7952902, -111.9191448](#)  
[View Image](#)



2025-06-03 12:23:35  
[40.7952902, -111.9191448](#)  
[View Image](#)

## Living Room

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Door/Knob/Lock     | ✓ S       | None    |         |
| Flooring/Baseboard | ✓ S       | None    |         |
| Light Fixture/Fan  | ✓ S       | None    |         |
| Other              | ✓ S       | None    |         |
| Switch/Outlet      | ✓ S       | None    |         |
| Wall/Ceiling       | ✓ S       | None    |         |
| Window Covering    | ✓ S       | None    |         |

| Detail | Condition | Actions | Comment |
|--------|-----------|---------|---------|
|--------|-----------|---------|---------|

Window/Lock/Screen

✓ S

None



2025-06-03 11:54:57

40.7951744, -111.9190971

360 Viewer



2025-06-03 11:55:21

40.7951744, -111.9190971

360 Viewer



2025-06-03 12:20:02

40.7952719, -111.919172

View Image



2025-06-03 12:20:08

40.7952719, -111.919172

View Image



2025-06-03 12:20:21

40.7952886, -111.9191591

View Image



2025-06-03 12:20:27

40.7952886, -111.9191591

View Image

Personal Property: Abandoned Property .

| Detail | Condition | Actions | Comment |
|--------|-----------|---------|---------|
| Other  | ✓ S       | None    |         |

Systems

| Detail                  | Condition | Actions | Comment |
|-------------------------|-----------|---------|---------|
| Air Conditioning/Filter | ✓ S       | None    |         |
| Breaker Box             | ✓ S       | None    |         |
| Furnace                 | ✓ S       | None    |         |
| Main Water Shut Off     | ✓ S       | None    |         |
| Paint On Site           | ✓ S       | None    |         |
| Sprinkler/Timer         | ✓ S       | None    |         |
| Thermostat              | ✓ S       | None    |         |
| Water Heater            | ✓ S       | None    |         |



2025-06-03 13:48:17  
40.7952727, -111.9191142  
[View Image](#)



2025-06-03 13:48:28  
40.7952727, -111.9191142  
[View Image](#)



2025-06-03 13:48:33  
[40.7952727, -111.9191142](#)  
[View Image](#)

#### Additional Comments

Screen on north exterior door needs replacement, tree branch grown into power line to house, I couldn't find switch to laundry room lightbulb (I replaced lightbulb). Furnace filter replaced, not something we can reasonably ask most tenants to do (unless they are plumbers)

#### Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

#### Agent / Inspector Signature